ABSOLUTE TIME ERROR CALIBRATION OF GPS RECEIVERS USING ADVANCED GPS SIMULATORS

E.D. Powers and M. Miranian United States Naval Observatory 3450 Massachusetts Ave., NW Washington DC 20392-5420 USA Tel 202-762-1451 fax 202-762-1511 E-mail powers@drake.usno.navy.mil

J.D. White and J. Brad United States Naval Research Laboratory 4555 Overlook Ave. SW, Code 8151 Washington DC 20375 USA

Abstract

Precise time transfer experiments using GPS with time stability's under ten nanoseconds are commonly being reported within the time transfer community. Relative calibrations are done by measuring the time error of one GPS receiver versus a "known master reference receiver." This relative calibration can produce very stable results, but this begs the question of "how does one calibrate the master reference GPS receiver."

In this paper we will discuss the use of advanced GPS simulators to measure the absolute time error of GPS receivers. This method has the advantage of calibrating a GPS receiver independent of any GPS system biases. The use of a GPS simulator also allows testing of special conditions of the GPS system, such as year 2000 rollover and the 1024 week epoch rollover.

INTRODUCTION

With the advent of the Global Positioning System (GPS), the Precise Time and Time Interval (PTTI) community has seen great advances in the ability to compare time and frequency at great distances. In practice, relative time transfer between two timing laboratories has achieved stabilities of a few nanoseconds with averaging times of only a few days [1]. Absolute time transfer between two timing laboratories is achieved by comparing one master timing GPS receiver to a secondary receiver over a period of time at a common location. Then the secondary timing GPS receiver is relocated to a remote timing laboratory to conduct the time transfer experiment. It is assumed that this hardware delay calibration of the secondary receiver will remain fixed.

maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to ompleting and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding ar DMB control number.	ion of information. Send comment arters Services, Directorate for Info	s regarding this burden estimate or or street	or any other aspect of the property of the contract of the con	nis collection of information, Highway, Suite 1204, Arlington		
1. REPORT DATE DEC 1997		2. REPORT TYPE		3. DATES COVE 00-00-199 7	red 7 to 00-00-1997		
4. TITLE AND SUBTITLE					5a. CONTRACT NUMBER		
Absolute Time Error Calibration of GPS Receivers Using Advanced GPS Simulators					5b. GRANT NUMBER		
					5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S)				5d. PROJECT NUMBER			
					5e. TASK NUMBER		
					5f. WORK UNIT NUMBER		
	ZATION NAME(S) AND AE atory,3450 Massach C,20392	` '		8. PERFORMING REPORT NUMB	G ORGANIZATION ER		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)					10. SPONSOR/MONITOR'S ACRONYM(S)		
					11. SPONSOR/MONITOR'S REPORT NUMBER(S)		
12. DISTRIBUTION/AVAIL Approved for publ	ABILITY STATEMENT ic release; distributi	on unlimited					
	OTES 14. 29th Annual Pre ch, CA, 2-4 Dec 199		e Interval (PTTI)	Systems and	Applications		
14. ABSTRACT see report							
15. SUBJECT TERMS							
16. SECURITY CLASSIFIC	17. LIMITATION OF	18. NUMBER	19a. NAME OF				
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	OF PAGES 8	RESPONSIBLE PERSON		

Report Documentation Page

Form Approved OMB No. 0704-0188 The hardware delay in the GPS receiving equipment is one of the major sources of uncertainty and instability for these types of time transfer experiments. By using advanced GPS satellite simulators to characterize GPS timing receivers, the uncertainties could be reduced to less than one nanosecond.

Multi-channel GPS simulators that can be used as ideal signal sources for GPS timing receiver calibration are now being produced by many companies. Advanced GPS satellite simulators can produce the same RF conditions that are received from a live GPS satellite, but in a controlled and repeatable manner. In addition, these GPS simulators can be used to characterize a GPS receiver's performance under a wide variety of conditions. Troposphere, ionosphere, multi-path, and selective availability errors can be controlled or set to zero. Any date and time can be simulated to determine whether a GPS receiver can cross-critical date/time boundary conditions such as the coming GPS 1023 epoch rollover. A GPS simulator scenario can be repeated many times to judge the repeatability of the GPS timing receiver. This may be done over a wide variety of environmental conditions to characterize the receiver's stability.

SIMULATOR HARDWARE CALIBRATION

The first step in achieving a highly accurate GPS receiver timing calibration is to calibrate the calibration equipment. To calibrate the GPS simulator, the relationship of the one pulse-per-second (1 PPS) reference signal from the simulator and the code phase of the generated GPS signal must be measured. The bi-phase modulated GPS signal code transition occurs in a finite bandwidth and is modulated by timing pulses with rise times of several nanoseconds. Figure 1 shows a high-speed digital oscilloscope plot of an amplified GPS L1 carrier modulated with CA code near the time of the reference one pulse per second. The effect of C/A code modulation (with the navigation data turned off) is that the amplitude of the carrier at the actual time of the reference pulse goes nearly to zero. The ability to properly interpret this code transition is the major limiting factor in this calibration technique.

After calibration, some simulators such as the STel 7200 have the ability to adjust the reference timing pulse output phase to reduce this error to zero. The Northern Telecom model STR2760 simulator precise timing output cannot be adjusted, but this difference can be carried as a paper calibration adjustment to be removed from the final receiver calibration value.

For the purpose of this paper, three ten-channel/satellite Northern Telecom model STR2760 (NT2760) GPS simulators were used. Experience with the NT 2760 simulator has shown that from a cold start, and without running the internal self-calibration recommended by the manufacturer, there can be 10's of nanoseconds of total delay variation and comparable code phase differences between the L1 and L2 signals. Using the NT internal self-calibration procedure before the start of each simulation will reduce the total delay variations to a few nanoseconds and the L1 to L2 variations to about one nanosecond. Table 1 shows the results of our external simulator calibration after the internal calibration has been run for NT simulator serial number 147 over a period of several years. These results show that NT simulator has very repeatable delays when the internal calibration is used.

GPS RECEIVER HARDWARE CALIBRATION

Once the simulator has been calibrated, the GPS receiver is connected as shown in Figure 2. The use of cables with identical delays in the RF and reference lines simplifies calibration by matching delays in the test and reference paths. A standard GPS simulator scenario is created with a fixed position and nominal

ionosphere and troposphere. These factors are included since the modeled ionosphere and troposphere corrections in many receivers cannot be turned off. A standard GPS constellation is used with no errors in satellite positions or satellite clocks.

Date	L1 Delay (nsec)	L2 Delay (nsec)
2/23/95	99.7	100.9
3/3/95	98.8	100.3
6/18/97	96.8	97.9
10/4/97	98.4	99.2
10/797	99.6	99.6
10/14/97	100.0	100.0

Table 1. Simulator Calibration Data, C/A codes.

The next step in the calibration process is to determine the average measured time difference between the calibrated GPS simulator and the timing GPS receiver outputs. The final step is to apply the appropriate bookkeeping delay corrections for the simulator bias, test cables delays, and the delays for the antenna and antenna cable.

STANFORD TELECOM SIMULATOR CALIBRATION METHOD

Stanford Telecom has their own version of this simulator calibration method and has used it successfully to calibrate the masters USNO GPS/UTC monitor receivers [2]. The USNO master GPS/UTC monitor receiver has a built-in calibration mode that is compatible with a calibration function of the STel 7200 GPS signal simulator. This allows for a more precise calibration than would normally be possible.

SIMULATOR CALIBRATION TEST RESULTS OF AOA TTR-4P

Several attempts to calibrate the Allen Osborne Associate (AOA) Model TTR-4P have been performed since 1995. The calibration data show a run-to-run variation that is significantly larger than the standard deviations of the individual tests. These variations could be as large as 20 or more nanoseconds. Initially some of the changes were thought to have been correlated with temperature changes in the laboratory. To isolate temperature effects, the AOA TTR-4P receiver was placed in a thermal chamber and re-tested at several temperatures. No clear temperature effect was identified, although some of the data pointed to coefficients as large as 1 nanosecond per degree Celsius. In late 1995 it was concluded that more detailed testing was needed to document what temperature effects exist and whether or not they are unique to this particular receiver or whether they are generic to the TTR-4P design.

The simulator did not appear to be the cause of the shifts, since its calibration number had remained constant over time and a variety of laboratory conditions. However, to increase confidence in it, another experiment was done using a STel 5401C receiver. The scenario length was increased to one day to increase the chance of seeing any irregularity in the simulator signal. The room temperature was changed

from 21°C to 27°C for several hours and then back to 21°C during the run. Within the noise limits of the STel receiver (less than 5 nanoseconds), no changes in the simulator were seen.

In 1996 USNO reported an error in the AOA TTR-4P resulting from the phase relationship between the external 5 MHz provided to the AOA TTR-4P and the measured local 1 PPS signal. It was thought that the relationships of the external 5 MHz signal and 1 PPS must be held fixed and have no bias to produce consistent time transfer results. This would later be proved only partially correct.

In June of 1997 AOA TTR-4P serial number 164 was made available for further simulator calibration testing. A series of detailed experiments were conducted investigating the relationship of the external 5 MHz and 1 PPS signals. The externally provided 5 MHz was offset by 1 mHz to study in detail this USNO reported phase effect. It was discovered that there was indeed a large error resulting from the phase relationship of the externally provided 5 MHz and 1 PPS. Figure 3 shows a time series plot of the measured 1 PPS signal output from the TTR-4P and the internally derived measurements. An obvious measurement error can be seen in these data of up to 24.4 nanoseconds. The period of each cycle shift is not 1000 seconds as might be expected, because the external 5 MHz is multiplied inside the receiver to a frequency of 20.456 MHz. All measurements within the AOA TTR-4P are based on this 20.456 MHz internal clock. The 24.4 nanosecond amplitude of the time error results from a 0 – 180 degree phase shift in this 20.456 MHz signal.

Next, the externally provided 5 MHz reference frequency offset was set to zero and its phase relationship was set to match the externally provided 1 PPS signal to less than 100 picoseconds. The receiver was then reset many times and allowed to acquire the simulated GPS signal. Table 2 shows the results of this experiment. There were many times when the receiver came back to within a few nanoseconds of its previous value; then there were other times the receiver jumped ten or more nanoseconds to a new calibration value. The receiver seems only able to be calibrated to within a 24.4 nanosecond window of uncertainty.

Time	AOA TTR-4P Delay in (nsec)
11:30	-162
11:39	-158
11:41	-160
11:43	-154
11:45	-152
11:49	-149
11:53	-170

Table 2. AOA TTR-4P Simulator Calibration Data

To confirm these simulator experiments two AOA TTR-4P receivers were run on live GPS satellites for several months and common-view data collected. Several times during this experiment, one of the TTR-4P's was reset and the time bias changed in a way similar to the simulator calibration results. Figure 4 shows one of the resulting time bias changes in the receiver after a reset.

GPS BOUNDARY CONDITION TESTING

The NAVSTAR GPS Joint Program Office (JPO) funds a consortium of DOD agencies called the Joint Test Agency Test Group (JTAWG). The Satellite Simulator Control Working Group (SSCWG) subpanel of the JTAWG was charged with creating a satellite simulator validation test plan and GPS receiver validation test plan for specific time boundary rollover conditions. The SSCWG members tasked with creating and accomplishing these test plans were the 746th Test Squadron (TS), Naval Research and Development (NRaD) San Diego, Naval Research Laboratory (NRL), and Electronic Proving Ground (EPG).

Listed below are the boundaries and navigation variables, which are being tested.

- 1. GPS epoch rollover from GPS epoch 0, week 1023, 21 Aug 1999 to GPS epoch 1, week 0, 22 Aug 1999.
- 2. GPS year 2000 rollover from December 31, 1999 to January 1, 2000.
- 3. GPS leap year rollover from February 28 to 29, 2000.
- 4. GPS Almanac Week boundaries

GPS 1024 WEEK EPOCH PROBLEM

The GPS week number is contained within the GPS NAV message in the form of a ten-bit binary number with a maximum decimal value of 1023, base epoch 0 or (11 1111 1111). This 1024-week period is commonly referred to as the GPS epoch. Rollover of this GPS week number may cause anomalous date determination within GPS receivers. The GPS Z-count has no provisions for determining which epoch is current. Week 0 of the first GPS epoch was defined as beginning 0000 hours January 6, 1980 the first crossover from week 1023-to-0 will occur 19.7 years later at 0000 on August 22, 1999. The GPS data structure does not contain information that would allow a GPS receiver to resolve which GPS epoch it is in. In GPS ICD-200 it states that "At the expiration of GPS week 1023, the GPS week number will rollover to zero (0). Users must account for the previous 1024 weeks." [3, 4]

GPS 1023 WEEK EPOCH TESTING

GPS simulators are the only testing tools available that can be used to determine if a GPS receiver will perform properly before, during and after this upcoming GPS 1023-week epoch crossover. Several timing GPS receivers were tested to determine if they would operated properly crossing this GPS 1023-week epoch crossover. We found that almost all timing GPS receivers with firmware older that 1995 would not fully function properly crossing this 1023-week boundary. The most common problem was that the date would jump back to Jan 6, 1980. Another problem observed was that a receiver might not be able to find any satellites visible because it tries to propagate the GPS almanac backward 19.7 years. One receiver appeared to function crossing the boundary, but the UTC (USNO) to GPS time correction was computed incorrectly because of the 1024 week jump causing a 74-microsecond time error

FUTURE WORK

The simulator calibration technique is still under going further refinement. We plan to begin using a calibrated anechoic chamber to directly couple the simulated GPS signal directly into the GPS antenna.

This will remove the uncertainty in the calibration of the GPS antenna and greatly improve our error budget. We will be testing several new GPS receivers such as the Motorola encore, AOA TTR6 and the DOD Precision Light Weight GPS receiver (PLGR).

CONCLUSION

Calibrations of GPS timing receivers using advanced GPS simulators have the potential to achieve nanosecond level absolute time calibration accuracies. The major limiting factor from a simulator perspective is the measurement of the absolute delay between the modulated GPS signal and the simulator precise timing output. The overall limiting factor is stability of the GPS timing receiver under test. GPS simulators also can be used to test for special boundary conditions coming in the GPS system such as the 1024-week rollover and the year 2000 rollover.

- [1] W. Lewandowski 1994, "GPS Common-view Time Transfer" in Proceedings of the 25th Annual Precise Time and Time Applications and Planning Meeting (NASA Conference Publication 3267), pp. 133-148.
- [2] J. Brad, E. Powers, J. White, and P. Landis 1996, "Receiver Time Delay Calibration Using a GPS Signal Simulator" PLANS Guidance Symposium, Jan 1996.
- [3] GPS Standard Positioning Service System Specification, June 1995, second edition, GPS Joint Program Office.
- [4] ICD-GPS-200 Navstar GPS Space Segment/Navigation User Interfaces, Rev C, IRN-201-001, Oct 1995.




Figure 1. CA-code modulated GPS signal at L1 frequencies.




Figure 2. Timing GPS receiver calibration test setup.




Figure 3. AOA TTR-4P external offset frequency reference problem.




Figure 4. AOA TTR-4P abrupt calibration change at MJD 50728.